

1965 APR 29 22 50Z

1. CAMERA B 122 WAS USED IN MISSION 8013 FLOWN ON 27 APRIL 1965.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.
(SEE PARA B AND C).

COPIES RECEIVED		Act.	Re
1			
2			
3, 4			

Approved For Release 2008/02/06 : CIA-RDP78B04558A000900030095-6

-2-

IS MADE BETWEEN FRAMES 300/301. THE LAST 25 PERCENT OF BREAKDOWN PART 6 CONTAINS INTERMITTENT CREASES, FOREIGN MATTER, EMULSION LIFTS AND HANDLING MARKS. THERE IS A FOGGED AREA ON APPROXIMATELY 30 INCHES OF FILM NEAR THE MIDDLE OF BREAKDOWN PART 8. AT THE END OF PART 8 THERE IS A REPAIRED TEAR ADJACENT TO THE HEAT SPLICE. PLUS DENSITY SPOTS, RESEMBLING ROLLER CHATTER, ARE PRESENT ADJACENT TO BOTH FILM EDGES THROUGHOUT. MANY FRAMES CONTAIN EMULSION LIFTS AND PINHOLES.

C. 9L SIDE: THE SEVERE METERING PROBLEM ALSO OCCURRED ON THIS SIDE BEGINNING WITH FRAME 37 BUT TO A LESSER EXTENT THAN THE 9R. THE LARGEST FRAME OVERLAP ON THIS SIDE MEASURED 11.2 INCHES. TWO TRANSVERSE BANDS OF LESS DENSITY OCCUR 3 INCHES APART ON FRAME 2. SIX ROWS OF MINUS DENSITY DOTS, APPROXIMATELY 1.5 INCHES APART, OCCUR 5.8, 2.4, 4.2, 1.5, 3.5 AND 6.8 INCHES FROM THE OUTBOARD EDGE OF THE FILM. THE LATTER THREE ROWS END IN FRAME 90 WHILE THE FIRST ROW ENDS IN FRAME 150. THE REMAINING TWO ROWS CONTINUE THROUGH APPROXIMATELY FRAME 1800. A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 2085.

D. BOTH SIDES: INTERMITTENT STATIC DISCHARGES OCCUR ALONG ALL FILM EDGES THROUGHOUT. THERE WERE 2420 CAMERA CYCLES ON THIS MISSION.

E. THERE WERE NO MAJOR PROCESSING PROBLEMS ENCOUNTERED ON THIS MISSION.

3. POSITIVE:

A. PI SUITABILITY IS GOOD WHERE NOT HINDERED BY THE SEVERE METERING PROBLEM.

-3-

B. PRINTING AND PROCESSING OF THE 9L SIDE ARE GOOD. NO 9R POSITIVES WERE RECEIVED DUE TO THE SEVERENESS OF THE METERING MALFUNCTION. WHERE POSSIBLE, INTERPRETATION OF THE 9R SIDE WAS ACCOMPLISHED UTILIZING THE ORIGINAL NEGATIVE.

C. CLOUD COVER ESTIMATE COULD NOT BE DETERMINED ON THIS MISSION.

GP-1

S E C R E T

--END OF MESSAGE--

1